

2023
Hose Testing

Date Tested: May 6, 2023

Tested by: First Due Services

The following hoses have been removed from service and disposed of due to holes.

Hose ID #5033 5"x100'	Date of Manufacturer 3/2011
ID #5035 5"x110'	Date of Manufacturer 3/2011

The following hard suction has been removed from service and disposed of due to vacuum fail

Suction ID #HS-06	Date of Manufacturer 5/1999 (ladder truck)
-------------------	--

The following 3" hose has been removed from service and disposed of due to being older than 1987 and can no longer be tested. A total of 16 hoses.

3036	3034	3029	3035	3022	3033	3032	3020	3501	3023	3010	3008	3016
	3550	3018	3030									

Plan of correction.

The two lengths of 5" hose has been replaced with spare from the rack.

The hard suction that was removed from the ladder truck will not be replaced as this truck will not be used for water supply

The 16 lengths of 3" hose will be replaced by purchasing a total of 300' of 2.5" hose so 11-1-1 has a full load of hose.